Navajo Abandoned Uranium Mine Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.

Elkins AUM Sites

Navajo AUM Eastern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

May 2009

Elkins Mines 1 May 2009

Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable Mine ID: 326, 327 Map ID: E49 (326) E50 (327) **CERCLIS:** NNN 000 908 709 **NAMLRP: NOT ASSIGNED** New Mexico Mining and Mineral Division ID: NM0146 New Mexico Bureau of Geology and Mineral Resources: NNMK0055, 0057 **Local name / Aliases:** Elkins Group Chapter and local area: Baca/Haystack Chapter **Lat/Long:** 35.4284128672 N / -108.056147825 W (#326) 35.4294304399 N / -108.055260418 W (#327) Nearby road and highway: Route 19, Red Cliffs Road Local Post Office: Prewitt, NM Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Tribal Fee Land Allotment** Fee land **Public lands Private Bureau of Land Mgmt** State

Ownership and contact information:

No ownership was identified. The mine site property is classified as Bureau of Land Management. No residences were found within 0.25 miles of the site

Part II Site Observations

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None **200 feet to 0.25 mile:** None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None **200 feet to 0.25 mile:** None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None 0.25 miles to 4 miles: unk

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents.

Note information on mine ownership, period of operation, and type of mining operation.

The Elkins Mines consisted of 2 sites, AUM ID numbers 326 and 327, equaling a total area of 11,412.57 square meters. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear.

Part III Type, number and reclamation status of mine features

Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.

Reclamation status of the mine sites are currently unknown. No visible signs of reclamation were observed. Mining operations appear to be surface by drilling into bedrock and blasting rock from the top of the mesa. Waste piles were observed adjacent to the mines. No adits or other mine features were observed during the site visit.

Part IV Summary of radiological readings

Background Locations

#1 9,368 cpm #2 9,708 cpm #3 5,198 cpm

Mine site: Elkins (326)
- See Figures 1 and 2

Mine site: Elkins (327)
- See Figures 1 and 2

Nearby Structure Perimeter – None

Describe any other radiological measurements:

A total of 3,143 gamma radiation measurements were collected from the mine sites, ranging from 4,416 cpm to 423,104 cpm. The measurements are represented in Figures 1 and 2.

Part V Site sketch of all mine features and readings, including locations of all structures, sources of drinking water and any other important features and radiological readings.

Presented in Figures 1 and 2

Part VI Response Action Summary

Site Name(s): Elkins Mines **Chapter:** Baca/Haystack

Decision Criteria

Is there an unreclaimed waste pile at the site? yes

At what distance from the waste pile is the nearest residential structure located? 0.5 mile

At what distances from the waste pile are there potential drinking water sources? 0.33 mile

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? N/A

Is the cap/seal sufficiently degraded to create a concern about releases? N/A

At what distance from the cap/seal is the nearest domestic structure located? N/A

At what distance from the cap/seal is the nearest domestic drinking water source? N/A

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

No known reclamation

Part VII Photos



Photo 1. Elkins 326 Mine site, towards the north



Photo 2. Elkins 326 Mine site, BLM cadastral survey marker



Photo 3. Elkins 326 Mine site, drill steel stuck in bedrock, towards north



Photo 4. Elkins 327 Mine site, waste rock piles

Part VIII Contacts Reports and Information

Name_Stanley Edison
Title or official role (if any) Navajo EPA Superfund Program
Address PO Box 2946, Window Rock, AZ 86515
Telephone number(928) 871-6861
Information provided <u>General Background and Contact/Access Information</u>
Name
Title or official role (if any)
Telephone number
Information provided
Name
Title or official role (if any)
Telephone number
Information provided
Name
Title or official role (if any)
Telephone number
Information provided



